


# Ice Scraper WITH COB LED LIGHT

DEAR CUSTOMER,

Congratulations on your purchase of a FLIPO® product. FLIPO® offers a wide variety of unique products of the highest quality. To ensure the maximum performance of your product, please read and save these instructions.



## Operation:

To turn the scraper's COB light ON, push the button located at the handle's rear once. To turn the COB light OFF, push the button again.

## Battery Installation

1. Unscrew the handle from the scraper by twisting in a counter-clockwise manner.
2. Remove the plastic battery cartridge from the handle.
3. Insert 3 AAA batteries into the cartridge according to the polarity symbols located at the ends of the cartridge.
4. Insert the battery cartridge into the handle; arrows on the sides of the cartridge should be pointing up away from the handle's bottom.
5. Replace the handle by twisting in a clockwise manner into the scraper.

## CAUTION

1. Failure to insert batteries in the correct polarity, as indicated in the battery compartment, may shorten the life of the batteries or cause batteries to leak.
2. Do not mix old and new batteries.
3. For best results, use alkaline batteries.
4. Do not mix Alkaline, Standard (Carbon-Zinc) or Rechargeable (Nickel Cadmium) or (Nickel Metal Hydride) batteries.
5. Do not dispose of batteries in fire.
6. Batteries should be recycled or disposed of as per manufacturer's recommendations.
7. To maximize battery life, turn the scraper's light off when not in use.



**MADE IN CHINA**

Distributed by Flipo Group Limited

Questions or Comments?

Call (815) 223-9942/ Email info@flipo.com